

# RaceHub Version 4.0

## Version 4.0.0

---

### New or changed functionality

#### Wheelbase

Area	Description	ID
Torque	Increased max value on damping, friction, inertia, and cornering force assist. This allows you to add more of each effect if desired.  <i>Please note that your old values might have been changed. This ensures the wheelbase feeling doesn't change with the update.</i>	-
Torque	Increase resolution on the inertia, cornering force assist, and anti-oscillation sliders. This allows you to adjust the effect more precisely, moreover, the design aligns with the damping and friction sliders.  <i>Please note that your old values might have been changed. This ensures the wheelbase feeling doesn't change with the update.</i>	2620

#### RaceHub

Area	Description	ID
Steering Wheel	Support for Invicta steering wheel including 3 new dash layouts with support for different units.	576 1874 2300
Steering Wheel	Support for SimHub. <ul style="list-style-type: none"> <li>• Layouts – requires Asetek SimSports Invicta steering wheel.</li> <li>• Flag lights</li> <li>• Shift light</li> </ul> <i>Please note that you'll need SimHub version 9.5.0 or newer to use this feature.</i>	1441
Miscellaneous	Smaller user interface improvements.	2413 2621

Miscellaneous	Performance improvements.	-
---------------	---------------------------	---

## Bug fixes

Area	Description	ID
Torque	<p>Cornering Force Assist has little or no effect in the games. Therefore, the maximum value has been increased giving you more possibilities to feel the setting.</p> <p><i>Please note that your old Cornering Force Assist value might have been changed. This is to ensure that the wheelbase feeling doesn't change.</i></p>	2307
Torque	Fixed how the basic/advanced toggle works.	2414
Shift Lights	Fixed an issue where shift lights didn't work as they should while playing iRacing.	2687 2702
Miscellaneous	USB communication optimizations.	2302
Miscellaneous	Fixed an issue where the pedal profile import didn't import all the settings.	2686
Miscellaneous	Fixed an issue where the steering wheel profile import wasn't loaded properly.	2700 2357
Miscellaneous	Fixed an issue where you, in rare cases, couldn't save your wheelbase settings.	2627